


10 FOR 10

KEEP ALL YOUR DIGITS IN COUNT



- **KEEP HANDS AND FINGERS CLEAR OF POINT OF OPERATIONS SUCH AS CUTTING, BORING, PUNCHING, BENDING, FORMING, AND SHEARING ACTIONS.**
- **KEEP HANDS AND FINGERS CLEAR OF NIP AND PINCH POINTS.**
- **KEEP ALL MACHINE GUARDING IN PLACE AND IN GOOD WORKING ORDER.**
- **DO NOT BYPASS SAFETY DEVICES SUCH AS TWO-HANDED CONTROLS, LIGHT CURTAINS, PRESSURE SENSING DEVICES, INTERLOCKED SWITCHES, ETC.**
- **PREVENT MACHINE SURPRISES- TAKE THE TIME AND USE LOCKOUT/TAG OUT PROCEDURES.**
- **AVOID WEARING GLOVES, LOOSE FITTING CLOTHING, RINGS, AND OTHER JEWELRY THAT COULD BE CAUGHT IN MACHINERY.**